

Exploration of the Feasibility of Production Rolling an Optimum Aluminum Alloy System Which Has an As-Welded Yield Strength of 30 KSI Minimum



FINAL REPORT

R.W. Rogers, Jr.

W.D. Vernam

M.B. Shumaker

Aluminum Company of America

Alcoa Laboratories

ALCOA

Contract N00024-74-C-5241 issued by Naval Sea Systems Command Project Serial Number SF541-702 Task 17350-21

De Contractor de la con

COPY

□ September 22, 1976

96

DERIGHTHON STATEMENT A

EXPLORATION OF THE FEASIBILITY OF PRODUCTION ROLLING AN OPTIMUM ALUMINUM ALLOY SYSTEM WHICH HAS AN AS-WELDED YIELD STRENGTH OF 30 KSI MINIMUM

by

R. W. Rogers, Jr. W. D. Vernam M. B. Shumaker

Contract N00024-74-C-5241 Sued by
NAVAL SEA SYSTEMS COMMAND

Project Serial Number SF541-702 Task 17350-21

Final Report

R. W. Rogers, Jr. Project Engineer H. Y. Hunsicker Project Supervisor

September 22, 1976

AND SAME ESTABLISH OF SPECIAL PARTY OF SPECIAL

ALUMINUM COMPANY OF AMERICA ALCOA LABORATORIES PHYSICAL METALLURGY DIVISION ALCOA TECHNICAL CENTER

Distriction of the property of

TABLE OF CONTENTS

	Page Num	nber
FOREWORD	. iii	
SYNOPSIS	. iv	
INTRODUCTION	. 1	
FABRICATION OF CS19 PLATE	. 4	
Ingots	. 6	
INITIAL EVALUATION OF CS19 PLATE	. 9	
Tensile Properties of Plate Exfoliation Resistance of Plate Tensile Properties of Weldments Summary of Initial Evaluation	. 11	
CS19 PLATE PROPERTIES	. 17	
Tensile Properties	. 17	
CS19-H3E19 Plate	. 17	
Temperature Exposure	. 17	
Fracture Toughness	. 21	
CS19-H3E19 Plate	. 21	
Corrosion Resistance	. 23	
CS19-H3E19 As-Fabricated Condition .	. 23	
Exfoliation Resistance	. 23	
Sea Water		
CS19-H3E19 After Elevated Temperature Exposure		
Exfoliation Resistance	. 39	
Sea Water	. 40	

	Page Number
CS19-O Plate	41
Resistance to General Corrosion in	
Sea Water	41
CS19-H3E19 PLATE WELDMENTS	43
COLD-HOLLY FLATE WELDPIENTS	43
Tensile Properties	44
As-Welded Condition	4.4
After Elevated Temperature Exposure	
	. Arapat
Fracture Toughness	47
Weld Ductility	49
Weld Ductility	49
As-Welded Condition	51
ns werded condition	
Exfoliation Resistance	51
SCC Resistance	
Designation of the Company Commercial in	31
Resistance to General Corrosion in	50
Sea Water	52
After Elevated Temperature Exposure	52
Exfoliation Resistance	57
SCC Resistance	
	31
Resistance to General Corrosion in	
Sea Water	63
SUMMARY	66
SUMMARI	00
CONCLUSIONS	69
REFERENCES	71
APPENDIX	72

FOREWORD

This report covers work done by the Aluminum Company of America at its Davenport Works and Alcoa Technical Center under Contract N00024-74-C-5241 issued by Naval Sea Systems Command. The Technical Supervisor for NAVSEA was Mr. T. C. West.

Plate fabrication at Davenport Works was supervised by Mr. R. W. Westerlund. Tensile and fracture toughness testing was directed by Mr. F. G. Nelson, Jr.; welding by Mr. G. P. Yanok; and metallographic studies were made by Mr. D. C. Sargent.

The cooperation and assistance of International Nickel Company's Francis L. LaQue Corrosion Laboratory at Wrightsville Beach, North Carolina, in conducting the sea water corrosion tests is greatly appreciated.

SYNOPSIS

A high-strength weldable aluminum-magnesium alloy, CS19, developed previously on an exploratory basis for ship structure applications was fabricated into plate from large ingots on production rolling mills to evaluate the feasibility of production rolling this alloy. Plate in 6.3 mm (.250") and 25.4 mm (1.0") thicknesses was produced from two commercial sizes of ingot with no difference in product characteristics observed between plates fabricated from either size or from smaller laboratory-cast ingots.

Tensile, notch-tensile, and corrosion tests of 25.4 mm CS19 plate and weldments confirmed the results of tests on laboratory-rolled plate of the same thickness to the effect that CS19 had an as-welded minimum tensile yield strength of 207 MPa (30 ksi) and corrosion and fracture toughness properties equivalent to or better than the current 5456-H116 or H117 alloys. As in the earlier work, CS19 was indicated to have a more rapid rate of stress-corrosion crack growth than 5456 under certain conditions but equal resistance to SCC initiation.

The thinner 6.3 mm CS19 plate and weldments had higher strengths than 25.4 mm plate and weldments but lower toughness; the latter, however, was judged to be equivalent to that of 5456-H117 of the same thickness. Corrosion resistance of the 6.3 mm plate and weldments was also good, except for SCC resistance of weldments after thermal treatments simulating the effects of long periods of service. Here the conditions of greater strain in the thinner plate produced a heat-affected zone structure which was susceptible to SCC but only after thermal treatment.

INTRODUCTION

In recognition of the need for a higher strength aluminum structural alloy for high-speed marine vessels, the Navy Ship Systems Command in 1972 issued a contract (N00024-72-C-5571) to Alcoa for test and exploratory development of a work-hardenable aluminum alloy plate material which was to have an as-welded minimum tensile yield strength of 207 MPa (30 ksi) and corrosion and fracture toughness properties equivalent to or better than those of present 5456-H116 or H117 alloys.

The result of this work (1) was an alloy designated CS19 whose composition was tentatively established as:

Mg	Mn	Cr	<u>Fe</u>	Si	Others
7.75-8.75	.3050	.0520	.12*	.10*	.05*
		*maximum			

CS19 plate was shown to produce weldments of 10% higher yield strength than 5456 and which readily met the 207 MPa minimum as-welded yield strength criterion; fracture toughness of CS19 plate and weldments was at least equivalent to that of 5456. Resistance to general and exfoliation corrosion of CS19 plate and weldments was also judged equivalent or superior to 5456. The resistance to stress-corrosion cracking of plate and weldments was considered

equivalent to that of 5456 with the exception of more rapid crack growth in as-fabricated CS19 plate stressed in the short transverse direction using precracked specimens loaded to very high stress intensity (tension pop-in). For most of this work including all of the weldment evaluations, 25.4 mm (1.0") plate from laboratory-cast ingots was employed.

To explore the feasibility of production rolling the alloy selected from the test and exploratory development contract, Navy Ship Systems Command on January 22, 1974, issued Contract N00024-74-C-5241 to Alcoa to undertake a production plate evaluation. For this phase, Alcoa had proposed to do the following: (2)

- (1) Cast production size CS19 ingots in two sizes: 300 mm x 960 mm x 3050 mm and 460 mm x 1520 mm x 3800 mm (12" x 38" x 120" and 18" x 60" x 150").
- (2) Roll on production rolling mills each size of ingot into the following thicknesses and tempers of plate:
 - (A) 25.4 mm (1.0") H3E19
 - (B) 25.4 mm (1.0") H1E48
 - (C) 6.3 mm (.250") H3E19
 - (D) 6.3 mm (.250") H1E48
 - (E) 6.3 mm (.250") H2E38
- (3) Evaluate all ten items for transverse tensile properties and exfoliation resistance of plate and tensile properties of full section weldment specimens.
- (4) Complete testing of items in each thickness which met the requirements of the initial

evaluation program for the following:

- (A) tensile properties
 - (i) as-fabricated

 - (iii) annealed
- (B) notch-tensile properties
- (C) corrosion resistance
 - (i) as-fabricated
 - (a) exfoliation
 - (b) SCC
 - (c) general
 - (ii) after elevated temperature
 storage
 - (a) exfoliation
 - (b) SCC
 - (c) general
 - (iii) annealed temper
 - (a) general
- (5) Produce GMA (MIG) weldments of one item in each thickness and perform the following tests:
 - (A) tensile properties
 - (i) as-welded reduced section
 - (ii) after elevated temperature
 storage
 - (B) notch-tensile properties
 - (C) bend tests
 - (D) corrosion resistance
 - (i) as-welded
 - (a) exfoliation
 - (b) SCC
 - (c) general
 - (ii) after elevated temperature
 storage
 - (a) exfoliation
 - (b) SCC
 - (c) general

FABRICATION OF CS19 PLATE

Ingots

The 300 mm x 960 mm x 3050 mm (12" x 38" x 120" ingots were cast at Alcoa Technical Center and the 460 mm x 1520 mm x 3800 mm (18" x 60" x 150") ingots at Davenport Works. No problems were encountered in casting these ingots; results of spectrographic analyses of cast sample specimens are listed in Table 1.

Examination of macroetched sections sawed from the head ends of one ingot of each size showed average grain diameter to be 0.8 mm (1/32") for the 300 mm \times 960 mm ingot and 3.2 mm (1/8") for the 460 mm \times 1520 mm. The finer grain size of the former can be attributed to faster chilling rate in casting and to grain refining effect of Ti.

Before homogenizing, the ingots were machined (scalped) to 267 mm (10.5") and 419 mm (16.5"), respectively, to remove approximately 19 mm (3/4") per rolling face. All ingots were ultrasonically inspected and found to be sound and suitable for rolling.

The homogenizing treatment produced a thermal soak of eight hours minimum at 496°C metal temperature prior to cooling to 425°C rolling temperature.

Hot Rolling - 25.4 mm (1.0") Plate

The H3E19 rolling practice calls for no particular temperature control during hot rolling, but requires a subsequent stretching operation to achieve desired strength levels.

TABLE 1

CHEMICAL COMPOSITION OF CS19 PRODUCTION INGOTS
FOR CONTRACT NO0024-74-C-5241

Identification	Size	Produced at	Number	_Mg_	Mn	Cr	Fe	Si	Zn	Ti	Ве
S-422050A	300 mm × 960 mm × 3050 mm (12" × 38" × 120")	ATC	1	8.60	0.39	0.11	0.06	0.05	0.05	0.02	0.001
S-422050B	300 mm x 960 mm x 3050 mm	ATC	1	8.40	0.40	0.11	0.06	0.05	0.01	0.03	0.001
S-422050C	300 mm x 960 mm x 3050 mm	ATC	1	8.22	0.42	0.11	0.06	0.05	0.01	0.02	0.001
S-422050D	300 mm x 960 mm x 3050 mm	ATC	1	8.51	0.39	0.10	0.06	0.05	0.00	0.02	0.001
Н951-01	460 mm x 1520 mm x 3800 mm (18" x 60" x 151")	Davenport	3	8.42	0.33	0.10	0.07	0.08			0.001

Values listed are spectrographic analyses of cast sample plates.

The H1E48 temper, on the other hand, requires plate to have its final hot rolling passes at 280°C in order to finish at 260-275°C with subsequent rapid cooling by mill coolant solution to below 200°C; a lesser degree of stretching is required. The H3E19 practice is a more desirable practice from the standpoint of hot mill productivity.

The ingots were initially cross-rolled on a 4 m (160") hot mill to widths of 1460 mm (57.5") and 2220 mm (87.5") for 300 mm x 960 mm and 460 mm x 1520 mm ingots, respectively, prior to lengthwise rolling to 25.4 mm (1.0"). No end preparation of the ingots was required prior to rolling and a moderate degree of alligatoring was encountered. Edge quality (maintained by edge rolling) and surface quality were excellent.

Hot Rolling - 6.3 mm (.250") Plate

Starting stock was part of the 25.4 mm plate rolled previously which was reheated to 425°C prior to the additional rolling to thinner plate thicknesses. Both H3E19 and H1E48 tempers were produced in 6.3 mm (.250") thickness with the same temperature restrictions employed for the thicker plates. No problems with edge cracking were encountered.

Cold Rolling - 6.3 mm (.250") Plate

The H2E38 temper was produced by cold rolling a 9.8 mm (.385") plate to 6.3 mm (.250") followed by an eight-hour soak at 246°C stabilizing thermal treatment. The 9.8 mm

plate was also produced by hot rolling pieces of 25.4 mm CS19 plate rolled previously. No edge cracking was encountered in cold rolling the 35% reduction, but many passes were required because of the high level of hardness developed in an alloy with such a high Mg content.

Finishing

No stretching problems were encountered in plate produced from the larger 460 mm x 1520 mm ingot, but plates from the 300 mm x 960 mm ingot broke before the complete stretch had been accomplished. A lower yield strength in H3E19 plate from this ingot size was attributed to this.

The fabricating practices employed are summarized in Table 2. The concensus of operating personnel following the plant trial was that production of CS19 plate was feasible but increased operating difficulties and more rolling passes, compared to 5456, could be anticipated.

TABLE 2 FABRICATING PRACTICES FOR CS19 PLATE ROLLED AT DAVENPORT WORKS OF ALCOA

Order:		TI	NS-C3534-	AW			T	NS-C3534-	-AX	
Item:	1	3	5	6	7	1	3	5	6	7
	25.4 mm	25.4 mm	6.3 mm	6.3 mm	6.3 mm	25.4 mm	25.4 mm	6.3 mm	6.3 mm	6.3 mm
	(1.000")	(1.000")	(.250")	(.250")	(.250")	(1.000")	(1.000")	(.250")	(.250")	(.250")
	H3E19	H1E48	H3E19	H1E48	H2E38	H3E19	H1E48	H3E19	H1E48	H2E38
Lot Number:	403-931	404-121	210-621	210-622	210-623	210-611	404-061	210-612	210-613	210-614
Ingot Size:	300 mm x	960 mm x	3050 mm (12" × 38"	x 120")	460 mm x	1520 mm x	3800 mm	(18" x 60"	x 150")
Scalped to:		267 1	mm (10-1/	2 ⁿ)			419	mm (16-1)	/2 ")	
Hot Roll - Width:		1460	mm (57-1/	2")			2220	mm (86-3)	/4")	
Hot Roll - Width: Thickness:	25.4 mm			2") 25.4 mm		25.4 mm			25.4 mm	
Thickness:	25.4 mm		,		9.8 mm	25.4 mm				9.8 mm
	25.4 mm		,	25.4 mm	9.8 mm 6.3 mm		25.4 mm*		25.4 mm	9.8 mm 6.3 mm
Thickness:	25.4 mm		,	25.4 mm 6.3 mm**			25.4 mm*		25.4 mm 6.3 mm**	

^{*}Rolled from 41 mm to 25.4 mm at 282°C. **Rolled from 12 mm to 6.3 mm at 282°C.

INITIAL EVALUATION OF CS19 PLATE

In accordance with the contract proposal (2), all ten items of production-rolled plate were tested for transverse tensile properties and resistance to exfoliation; in addition, MIG weldments were prepared from each item and full section specimens tested for as-welded tensile properties. Results of these initial evaluations are reported below.

Tensile Properties of Plate

Results of transverse tensile tests for the ten items of plate fabricated from two sizes of production ingot at Davenport are listed in Table 3 together with similar data for laboratory-fabricated plate from the earlier exploratory development contract report. (1) These tests were made in accordance with ASTM Method E8. Results show that if the same fabricating procedures were employed for a given temper, the tensile properties were very similar regardless of ingot size employed and whether rolled on laboratory or production mills.

The strengths of the 25.4 mm thick plate were consistently lower than those of the 6.3 mm plate for similar tempers. This is a reflection of the higher equivalent cold work induced by hot rolling the thinner gauge plate. The low yield strength of S-438562 from 300 mm x 960 mm ingot was attributed to failure to achieve the full 4% stretch because of breakage in stretching.

TABLE 3

TRANSVERSE TEST RESULTS FOR CS19 PLATE FABRICATED BY LABORATORY AND PRODUCTION ROLLING PROCEDURES

			Amount	Number	A	verage Tr			le Properties
			of	of	Tensi	le Str.	Yield	d Str.	Elongation
Thickness	Temper	S. No.	Stretch	Tests	MPa	(ksi)	MPa	(ksi)	(% in 50.8 mm)
		150 mm	x 400 mm	< 900 mm	(6" x 1	6" x 36";) Ingo	t (1)	
6.3 mm	H1E48	421896	1.5%		451	(65.4)	272	(39.4)	25.0
(.250")	H2E38	421894	1.5%		449	(65.1)	252	(36.6)	13.5
	H3E19	421895	1.5%		436	(63.2)	250	(36.3)	24.0
25.4 mm	H1E48	416448	1.5%	2	411	(59.6)	244	(35.4)	21.5
(1.0")	H1E48	419453	1.5%	2	423	(61.4)	261	(37.8)	22.9
	H3E19	419453	4.0%	2	421	(61.1)	251	(36.4)	22.0
		300 mm	n x 960 mm	x 3050 mm	n (12"	x 38" x	120")	Ingot	
6.3 mm	H1E48	438628	1.5%	3	441	(63.9)	274	(39.8)	22.7
	H2E38	438726	1.5%	3	416	(60.3)	258	(37.4)	9.0
	H3E19	438564	1.5%	3	452	(65.6)	286	(41.5)	22.7
25.4 mm	H1E48	438563	1.5%	3	420	(60.9)	254	(36.9)	22.0
	H3E19	438562	(4.0%)	3	405	(58.8)	230	(33.4)	21.3
		460 mm	n x 1520 mr	n x 3800 n	nm (18"	x 60" x	150")	Ingot .	
6.3 mm	H1E48	438568	1.5%	3	435	(63.1)	288	(41.8)	21.8
	H2E38	438629	1.5%	3	397	(57.6)	226	(32.8)	12.0
	H3E19	438567	1.5%	3	438	(63.5)	282	(40.9)	21.7
25.4 mm	H1E48	438566	1.5%	3	412	(59.7)	247	(35.8)	21.8
	H3E19	438565	4.0%	3	405	(58.7)	248	(36.0)	22.7

Note: (1) Data for this ingot size from Reference 1 for laboratory-rolled plate.

In the 6.3 mm plate items, lower strengths of the H2E38 temper, especially S-438629, resulted from the precipitation treatment of eight hours at 246°C. Strengths of the H3E19 and H1E48 tempers were quite similar.

Exfoliation Resistance of Plate

The resistance to exfoliation of all ten items of production-rolled CS19 alloy plate was evaluated with the ASSET immersion test as recommended by the Aluminum Association Task Group on Exfoliation to replace both of the corrosion tests previously specified under Federal Specification QQ-A-00250/20 for alloy 5456. The results of the exfoliation tests performed on the 25.4 mm and 6.3 mm thick CS19 plate from the two production-size ingots are listed in Table 4 together with results for the laboratoryrolled 25.4 mm plate in the earlier test and exploratory development contract. (1) They indicate excellent resistance to exfoliation for both thicknesses of plate regardless of the size ingot. The resistance to exfoliation of both laboratory and plant-fabricated CS19 alloy plate was comparable to 5456 alloy plate, which was one of the key objectives of the contract.

Tensile Properties of Weldments

The tensile properties of full section (Fig. I in Appendix) specimens of the two tempers of plate produced in 25.4 mm thick plate are listed in Table 5 along with comparable data for the laboratory-produced plate of contract N00024-C-5571.

TABLE 4

ACCELERATED EXFOLIATION TEST (ASSET) RESULTS FOR CS19 PLATE FABRICATED BY LABORATORY AND PRODUCTION ROLLING PROCEDURES

			Exfoliation a	fter ASSET Test1
Thickness	S-No.	Temper	As-Fabricated	After One Week at 100C
	150 mm x 4	100 mm × 900	mm (6" x 16" x 36")	Ingot ²
6.3 mm	4218962	H1E48	N	N
(.250")	4218942	H2E38	N	P-A
	421895 ²	H3E19	N	N
25.4 mm	4194532	H1E48	N	N
(1.0")	4194532	H3E19	N	N
6.3 mm	300 mm x 9	960 mm x 3050 H1E48) mm (12" x 38" x 12 N	0") Ingot N
	448726	H2E38	N	N
	438564	H3E19	N	N
25.4 mm	438563	HlE48	N	N
	438560	H3E19	N	N
	460 mm x 1	1520 mm x 380	00 mm (18" x 60" x 1	50") Ingot
6.3 mm	438568	HLE48	P-A	N
	438629	H2E38	N	N
	438567	H3E19	P-A	N
25.4 mm	438566	H1E48	N	N
	438565	H3E19	N	N

Notes: (1) 24 hours total immersion in solution of 1N NH $_4$ Cl, 0.25 N NH $_4$ NO $_3$, 0.01 M ammonium tartrate and 3 g/l hydrogen peroxide at 66°C; N is no appreciable attack; P-A is slight pitting attack.

(2) Data for this ingot size from Reference 1 for laboratory-rolled plate.

CS19 filler electrode was employed for the production plate. As shown, the as-welded yield strengths were quite consistent and were essentially the same for both tempers of production plate produced from two ingot sizes and for the laboratory-rolled plate despite somewhat different parent plate yield strengths. The increase in parent plate yield strength obtained by stretching the production plate (4% for H3E19 and 1.5% for H1E48) was apparently lost from the heat of welding as it was not reflected in any increase in weldment yield strength.

The tensile properties of full section (Fig. I in Appendix) specimens of the three tempers of plate produced from 6.3 mm thick plate are listed in Table 6.

CS19 filler electrode was employed. It will be noted that the yield strengths of the 6.3 mm plate weldments are quite similar for H3E19 and H1E48 tempers; the higher yield strengths compared to those of 25.4 mm plate weldments reflect the higher strength of the thinner parent plate.

The inconsistent and erratic weld tensile strengths and elongation values are a reflection of the type of abnormal failures encountered in the fractured specimens. Such failures can be encountered when developing welding parameters for new or experimental alloys. For the most part, such failures are isolated and can be controlled through experience. Although these inconsistencies developed in the 6.3 mm plate

Id bead and fusion zone.

TABLE 5

TENSILE TEST RESULTS FOR WELDMENTS OF 25.4 mm (1.0") CS19 PLATE FABRICATED BY LABORATORY AND PRODUCTION ROLLING PROCEDUEES

		-	-	Parer	Parent Plate				Wel	Weldment?				
Тепрех	Temper S-No.	Ten	Tensile Str.		Yield Str.	* in 50.8 mm (2")		Tensile Str.		Yield Str.		Elong % mm 50.8 mm 254 mm (2") (10")	Location of Fracture	Type of Fracture
						150 mm x 400		.9) mm 006 x mm	. × 16"	" x 36"	x 36") Ingot3	6)		
HIE48	4164484		403 (58,5)	232	(33,6)	23.6	316	(45.9)	229	(33.2)	0.6	4	Zone of fusion	
	419453'	410	(59.4)	234	(34.0)	24.0	341	(48.9)	223	(32.3)	(25)	10 H		1 1
	426723*	39.8	(57,7)	223	(32, 3)	3 24.0	329	(45.2)	229	(33.2)	9.00	3.7	Zone of fusion Zone of fusion	111
						300 mm x 960	mm x 30	mm x 3050 mm (12" x	2" x	38" x 1	38" x 120") Ingot	got		
HIERA	438563	421	(61.1)	256	(37.2)	21.5	350	(80.8)	228	(33.0)	10.0	4.5	Zone of fusion	The first and th
		420	(60.9)	254	(36.8)	22.0	366	(53.1)	228	(33.0)		6.9	Zone of fusion	Lack of fusion fracture there.
	Avg.	450	(60.9)				359	(52.0)	228	(33.1)	9.5	4.7	Zone of fusion	Typical weld/parent interface fracture.
H3E19	438560	405	(58.8)				367	(53.3)	219	(31.8)	12.0	7.2	Zone of fusion	
	Avg.	402	(58.3)	229	(33.2)	22.0	352 347 356	(51.1) (50.3) (51.6)	218	(31.6)	10.5	6.8		Typical weld/parent interface fracture. Typical weld/parent interface fracture.
						460 mm x 1520	x ww		181 ×	×09	(18" x 60" x 150") Ingo	205		
HIE48	438566	416	(60.4)	246	(36.0)		363	(52.6)	226	(32.8)	13.0		Zone of fusion	Typical weld/parent interface fracture
	Avg.	410	(59.4)	247	(35.8)	21.0	356	(51.9)		(32.7)	12.0	7.0	Zone of fusion Zone of fusion	Typical weld/parent interface fracture. Typical weld/parent interface fracture.
R 3E 19	438565	402	(58.3)	251	(36.4)	22.5	366	(53.1)	219	(31.7)	13.5			Typical weld/parent interface fractore
	Avg.	405	(59.4)	252	(36.5)			(51.4)		(31.9)	13.2	7.4	Zone of fusion	Typical weld/parent interface fracture. Typical weld/parent interface fracture.
		Notes	Notes: (1)	Trans	Transpoyers tock	-								

3858

Transverse tests.
Longitudinal welds; full section boiler-plate specimens. Electrode alloy was CS19 type. Data for this ingot size from Reference 1 for laboratory-rolled plate,

TABLE 6

TENSILE TEST RESULTS FOR WELDMENTS OF 6.3 mm (.250") CS19 PLATE FABRICATED BY LABORATORY AND PRODUCTION ROLLING PROCEDURES

Type of Fracture	Lack of weld fusion. Lack of weld fusion. Lack of weld fusion.	Lack of weld fusion. Lack of weld fusion.	Typical weld/parent interface fracture. Lack of weld fusion. Typical weld/parent interface fracture.	Typical weld/parent interface fracture. Typical weld/parent interface fracture. Typical weld/parent interface fracture.	Small inclusion in weld bead. Lack of fusion and porosity. Small inclusion at toe of weld.	Lack of weld fusion. Typical weld/parent interface structure. Typical weld/parent interface structure.
Location of Fracture	Zone of fusion Zone of fusion Zone of fusion	Parent metal Zone of fusion Zone of fusion	Zone of fusion Zone of fusion Zone of fusion	Zone of fusion Zone of fusion Zone of fusion	Zone of fusion Zone of fusion Zone of fusion	Zone of fusion Zone of fusion Zone of fusion
d Str. 50.8 mm 254 mm (Ksi) (2") [10"]	5.0 1.2 2.5 0.8 6.0 2.2 4.5 1.2	10.0 6.3 5.5 2.3 5.0 2.1 6.8 3.6	(38.7) 10.0 5.1 (38.6) 5.0 1.5 (38.3) 8.5 4.4 (38.5) 7.8 3.7 60" x 150") Incot	6.5 2.4 6.5 2.2 6.0 2.2 6.3 2.3	7.5 3.5 5.5 2.7 5.5 2.2 6.2 2.8	8.5 3.6 13.5 8.0 12.0 7.7 11.3 6.5
d Str. (ksi) 38" x	270 (39.1) 261 (37.9) 268 (38.8) 266 (38.6)	251 (36.4) 250 (36.2) 247 (35.8) 249 (36.1)	267 (38.7) 266 (38.6) 264 (38.3) 265 (38.5) (18" x 60" x 1	255 (37.0) 257 (37.3) 256 (37.2) 256 (37.2)	228 (33.0) 226 (32.8) 228 (33.0) 227 (32.9)	260 (37.7) 263 (38.1) 265 (38.4) 263 (38.1)
Mea Tensile Str. Viel MPa (Ksi) MPa mm x 3050 mm (12" x	298 (43.2) 260 (37.7) 343 (49.8) 301 (43.6)	403 (58.5) 315 (45.7) 311 (45.1) 343 (49.8)	379 (55.0) 305 (44.3) 359 (52.1) 348 (50.5)	321 (41.6) 319 (46.2) 321 (46.6) 320 (46.5)	340 (49.3) 315 (45.7) 295 (42.8) 316 (45.9)	337 (48.9) 396 (57.4) 397 (57.5) 376 (54.6)
Elongation, % in 50.8 mm (2") 300 mm x 260	23.0 22.5 22.5 22.7	9.0	23.0 23.5 21.5 22.7 460 mm x 1520	21.0 22.0 22.0 22.0	10.5 9.5 16.0	21.5 22.0 21.5 21.5
Vield Str. MPa (ksi)	275 (39.9) 273 (39.7) 273 (39.7) 274 (39.8)	257 (37.3) 256 (37.2) 259 (37.6) 258 (37.4)	285 (41.3) 287 (41.6) 286 (41.5) 286 (41.5)	286 (41.8) 286 (41.5) 290 (42.0) 288 (41.8)	228 (33.0) 226 (32.8) 225 (32.7) 226 (32.8)	279 (40.5) 276 (40.1) 290 (42.1) 282 (40.9)
Tensile Str.	(63.6) (7 (64.8) (7 (63.4) (11 (63.9)	7 (62.0) 8 (57.7) 22 (61.2) 6 (60.3)	(65.7) (65.7) (65.5) (65.6)	(62.8) (63.1) (63.1)	(6 (57.5) (3 (57.0) (2 (58.3) (57.6)	(63.5) (62.5) (4 (64.4) (63.5)
S-No.	438628 439 447 437 Avg. 441	448726 427 398 422 Avg. 416	438564 453 453 451 Avg. 452	438568 433 435 438 Avg. 435	438629 396 393 402 Avg. 397	438567 438 431 444 Avg. 438
Temper	H1E48	Н2Е38	H3E19	H1E48	Н2Е38	H3E19

Notes: (1) Transverse tests.
(2) Longitudinal welds; full section boiler-plate type specimens. Electrode alloy was CS19 type.

weldments, all tempers exceeded the contract objective of 207 MPa (30 ksi) minimum as-welded yield strength.

Summary of Initial Evaluation

Results of this initial evaluation program indicated first of all that CS19 plate fabricated on production-rolling equipment from large-size ingots was very similar in strength to CS19 plate fabricated by similar practices but in the laboratory previously from smaller ingots.

The same was true for the strength of weldments and for resistance to exfoliation.

As will be discussed subsequently, other evaluations including stress-corrosion testing confirmed the equivalency of H1E48 and H3E19 tempers from the standpoint of corrosion resistance. Since the H3E19 temper fabricating practices were advantageous productionwise, it was decided to gather complete data for the two items in this temper for each thickness in the remaining contract work.

CS19 PLATE PROPERTIES

Tensile Properties

Longitudinal and transverse tensile properties of CS19 plate were determined in accordance with ASTM Method E8.

CS19-H3E19 Plate

Results are listed in Table 7 for the plates from two different ingot sizes in each thickness, 6.3 mm (.250") and 25.4 mm (1.0"). The greater amount of equivalent cold work retained in the hot-rolled 6.3 mm plate is reflected in its considerably higher level of strength even though the 25.4 mm plate had 4% nominal subsequent stretching versus 1.5% for 6.3 mm plate.

The lower yield strength of the 25.4 mm plate produced from the 300 mm x 960 mm ingot (S-438560) is attributed to its failure to obtain the full 4% stretch because of breakage in the stretching operation.

CS19-H3E19 After Elevated Temperature Exposure

Results of tensile tests after three periods of elevated temperature storage (30 days at 66°C, 7 days at 80°C, or 7 days at 100°C) are tabulated in Table 8. The thermal treatments produced slight losses in yield strength but little, if any, change in tensile strength. The largest yield strength loss was in the 25.4 mm plate (S-438565) which had received the most (4%) stretch.

TABLE 7
TENSILE PROPERTIES OF CS19 PLATE

			Amount of		Lo	ngitud	inal			Tr	ansver	se	
Thickness	S-No.	Ingot Size	Stretch	Tensile	Strength	Yield	Strength		Tensile	Strength		Strength	Elong.
			(%)_	MDm	(ksi)	MPa	(ks1)	(% in 50.8 mgm)	100				t in
			-1-1	MPa	(851)	mr d	1831/	Tag. 8 ugu	MPa	(ksi)	MPa	(ksi)	\50.8 nm)
					H3E1	9 Temp	er						
6.3 mm	438564	300 mm x 960 mm	1.5	478	(69.3)	340	(49,3)	16.0	452	(65.6)	286	(41.5)	22.7
(.250")	438567	460 mm x 1520 mm	1.5	452	(65.6)	314	(45.6)	15.2	438	(63.5)	282	(40.9)	21.7
25.4 mm	438560	300 mm x 960 mm	4.0	424	(61.5)	263	(38.2)	22.0	405	(58.8)	230	(33.4)	21.3
(1.0")	438565	460 mm x 1520 mm	4.0	419	(60.8)	269	(39.0)	22.0	405	(58.7)	248	(36.0)	22.7
					0	Temper							
						- Ciaper							
6.3 mm	438564	300 mm x 960 mm		395	(57.3)	187	(27.1)	28.2	392	(56.9)	186	(27.0)	28,5
	438567	460 mm x 1520 mm		374	(54, 3)	181	(26.2)	29.2	381	(55,2)	183	(26.5)	27.5
25.4 mm	438560	300 mm x 960 mm		407	(59.0)	196	(28.4)	27.5	405	(58.7)	193	(28.0)	27.8
	438565	460 mm x 1520 mm		401	(58.2)	198	(28.7)	25.3	390	(56.5)	192	(27.8)	26.7
5456-0 ³				310	(45.0)	159	(23.0)	24.0					~~

Notes: (1) All results are averages of three tests except longitudinal H3E19 which were single tests.

(2) Annealing treatment was one hour at 427°C (800°F).

(3) Typical values for 5456-0 from "Aluminum Standards and Data, 1976", The Aluminum Association. Thickness, test direction, and annealing temperature not specified.

TABLE 8

TENSILE PROPERTIES OF CS19-H3E19 PLATE AFTER EXTENDED PERIODS AT ELEVATED TEMPERATURES

Thickness	S-No.	Ingot Size	Condition	Tensile	Strength	Yield	Strength	Elongation
				MPa	(ksi)	MPa	(ksi)	(% in 50.8 mm)
6.3 mm	438564	300 mm x 960 mm	As-fabricated	452	(65.6)	286	(41.5)	22.7
(.250")			After 30 days at 66°C	449	(65.1)	282	(40.9)	21.5
			After 7 days at 80°C	452	(65.5)	281	(40.7)	21.5
			After 7 days at 100°C	451	(65.4)	280	(40.6)	20.8
	438567	460 mm x 1520 mm	As-fabricated	438	(63.5)	282	(40.9)	21.7
	7.77.7.7		After 30 days at 66°C	432	(62.7)	273	(39.6)	23.2
			After 7 days at 80°C	431	(62.5)	272	(39.4)	23.3
			After 7 days at 100°C	436	(63.3)	266	(38.6)	23.5
25.4 mm	438560	300 mm × 960 mm	As-fabricated	405	(58.8)	230	(33.4)	21.3
(1.0")			After 30 days at 66°C	414	(60.1)	222	(32.2)	24.0
(1.0)			After 7 days at 80°C	416	(60.3)	220	(31.9)	24.3
			After 7 days at 100°C	413	(59.9)	212	(30.7)	24.8
	438565	460 mm x 1520 mm	As-fabricated	405	(58.7)	248	(36.0)	22.7
			After 30 days at 66°C	401	(58.2)	230	(33.3)	24.7
			After 7 days at 80°C	400	(58.1)	224	(32.5)	24.8
			After 7 days at 100°C	400	(58.1)	217	(31.5)	25.2

Note: All results are averages of three tests for specimens cut in the long transverse direction.

In the laboratory-rolled 25.4 mm plate in the previous contract, no loss in yield strength after thermal treatments was reported. That plate, however, was not stretched and was in the equivalent of H1E48 temper (finish hot rolled at about 275°C). Considering all of these data, it would appear that the yield strength increase imparted by stretching as in the current material is reduced to some extent in extended thermal treatments designed to simulate the effects of metallurgical changes taking place over long periods of service.

CS19-O Plate

Two thicknesses of plate in the H3E19 temper were annealed by a treatment of one hour at 427°C. The tensile properties are also listed in Table 7. Annealed temper strengths are about 10% higher than those of typical 5456-0 but are below the 207 MPa (30 ksi) level which was the minimum for welded plate. While annealed plate yield strength above 207 MPa would be desirable to assure weldment yield strength greater than 207 MPa, the latter property is not entirely dependent upon the former. As shown subsequently, the target value of 207 MPa can be met by welding material having higher strengths than annealed material even though the annealed yield strength is below 207 MPa.

The greater degree of retained cold work in the 6.3 mm hot rolled plate is apparent here as lower strengths

after annealing which resulted from the higher degree of recrystallization achieved than was the case for 25.4 mm plate.

Fracture Toughness

CS19-H3E19 Plate

Notch-tensile tests were made in accordance with an ASTM draft method. Specimens with 60° edge notches were employed; specimens for the 6.3 mm plate were 12.7 mm wide, and for 25.4 mm plate, were 12.7 mm - diameter rounds.

Results are listed in Table 9 for the two CS19-H3E19 plates from two different ingot sizes in each thickness, 6.3 mm and 25.4 mm, as well as for one 25.4 mm stretched CS19-H1E48 plate from the earlier laboratory work. Also listed for comparison are notch-tensile test data for 6.3 mm 5456-H321 plate. (3)

From the current work it is indicated that the fracture toughness of this 25.4 mm production-rolled plate is comparable to that of the previous laboratory-rolled product of the same thickness. In the report on the latter (1), it was concluded that CS19 fracture toughness was at least equivalent to that of 5456. This view is supported by the comparisons here of NTS/YS results for 6.3 mm CS19-H3E19 with those for 6.3 mm 5456-H321.

The lower toughness of the 6.3 mm compared to 25.4 mm thickness is again attributed to the greater amount of equivalent cold work retained in the thinner hot-rolled plate.

TABLE 9 NOTCH TOUGHNESS OF CS19-H3E19 PLATE $^{\rm 1}$

Thickness	S-No.	Test Direction	MPa	Strength (ksi)	MPa	Strength (ksi)	Elongation (% in 50.8 mm)	Notch Ten	sile Strength ¹ (ksi)	NTS/YS
			150 mm x	400 mm x	900 mm (6" x 16" >	(36") Ingot			
25.4 mm (1.0")	416448	Longitudinal Transverse	430 411	(62.3) (59.6)	291 244	(42.2) (35.4)	16.2 21.5	480 439	(69.6) (63.7)	1.65
			300 mm x	960 mm x 3	050 mm (12" x 38"	x 120") Ingot			
6.3 mm (.250")	438564	Longitudinal Transverse	478 452	(69.3) (65.6)	340 286	(49.3) (41.5)	16.0 22.7	390 359	(56.5) (52.0)	1.15 1.25
25.4 mm	438560	Longitudinal Transverse	424 405	(61.5) (58.8)	263 230	(38.2) (33.4)	22.0 21.3	421 412	(61.1) (59.7)	1.60
			460 mm x	1520 гат х	3800 mm	(18" x 60'	' x 150") Ingot			
6.3 mm	438567	Longitudinal Transverse	452 438	(65.6) (63.5)	314 282	(45.6) (40.9)	15.2 21.7	390 362	(56.5) (52.5)	1.24
25.4 mm	438565	Longitudinal Transverse	419 405	(60.8) (58.7)	269 248	(39.0) (36.0)	22.0 22.7	464 452	(67.3) (65.6)	1.73
				Plant	Producti	on Ingot				
6.3 mm	5456-H321 ²	Transverse	370	(53.7)	256	(37.2)	19.5	303	(44.0)	1.18

Notes: (1) Averages of three tests.
(2) Results for three-inch wide edge-notched specimens per Reference 3.

Corrosion Resistance

Corrosion resistance of CS19-H3E19 plate was evaluated in regard to exfoliation susceptibility and stress-corrosion crack (SCC) susceptibility in laboratory-accelerated tests and to general corrosion susceptibility from quiescent and flowing sea water. Both plate in the as-fabricated condition and after elevated temperature exposures were tested.

CS19-H3E19 As-Fabricated Condition

Exfoliation Resistance

Evaluations of exfoliation susceptibility employing ASSET tests were carried out in the initial evaluation program and are reported in Table 4. These tests indicated excellent resistance to exfoliation for the CS19-H3E19 plate in both thicknesses as well as for all of the other CS19 plate tempers evaluated.

SCC Resistance

Long Transverse. Stress-corrosion resistance of the two thicknesses of CS19 alloy plate was evaluated in the long-transverse direction with 3.175 mm (.125") diameter tensile bars taken from the T/4 plane of the plate and full thickness beam assemblies. The results listed in Table 10 are for specimens stressed to 75% of their yield strength and exposed to the 3-1/2% NaC1 alternate immersion test (ASTM G44-75, Federal Test Standard 151b, Method 823).

TABLE 10

RESISTANCE TO STRESS-CORROSION CRACKING OF CS19 PLATE EXPOSED TO 3-1/2% Nacl SOLUTION BY ALTERNATE IMMERSION

			Beam Assemblies - Stressed 75% Y.S.				3.175 mm (1/8") Dia. Long Transverse Tensile Bars - Stressed 75% Y.S.				
				As-Fabricated		Heated 1 wk/100°C		As-Fabricated		Heated 1 wk/100°C	
Thickness	S-No.	Temper	F/N	Days to Fail	F/N	Days to Fail	F/N	Days to Fail	F/N	Days to Fail	
		30	O mm x	960 mm x 3050	mm (12	" x 38" x 120")	Ingot				
6.3 mm (0.250")	446286	H3E19	0/2	OK-290	0/2	OK-290	0/3	OK-289	0/3	OK-289	
	446287	H1E48	0/2	OK-290	0/2	OK-290	0/3	OK-289	0/3	OK-289	
	446595	H2E38	0/2	OK-290	0/2	OK-290	0/3	OK-289	0/3	OK-289	
25.4 mm (1.0")	438650	H3E19					0/3	OK-156	0/3	OK-156	
		460	mm x	1520 mm x 3800	mm (18	" x 60" x 150")	Ingot				
6.3 mm	446290	H3E19	0/2	OK-290	0/2	OK-290	0/3	OK-289	0/3	OK-289	
	446291	H1E48	0/2	OK-290	0/2	OK-290	0/3	OK-289	0/3	OK-289	
25.4 mm	446288	H3E19	0/2	OK-290	0/2	OK-290	0/3	OK-289	0/3	OK-289	
	446289	H1E48	0/2	OK-290	0/2	OK-290	0/3	OK-289	0/3	OK-289	

Note: (1) F/N denotes number of specimens failed over number of specimens exposed.

No evidence of SCC was observed after a significant exposure period of 290 days.

It will be noted that H1E48 plate was also evaluated for SCC resistance in both thicknesses with no susceptibility indicated for this temper either. This is consistent with the conclusion reached in the initial evaluation from exfoliation test results that H1E48 and H3E19 tempers were equivalent corrosionwise.

Short Transverse. The 25.4 mm (1.0") CS19-H3E19 plate was also tested in the short-transverse direction with 19.0 mm (.75") diameter C-ring specimens stressed to 75 and 50% of the long transverse yield strengths and exposed to the 3-1/2% NaCl alternate immersion test. The results (Table 11) show no evidence of SCC after a significant exposure period of 280 days. Previous test results for the test and exploratory development contract (1) indicated that both laboratory-fabricated CS19 and 5456 alloy plate showed no evidence of SCC after an exposure period of one year.

Fracture Mechanics-Type Specimens. Stress-corrosion tests were performed with the double cantilever beam specimens (Figure II in Appendix) using a beam height of 25.4 mm (1.0"). Duplicate short transverse specimens (S-L orientation) from 25.4 mm thick CS19-H3E19 temper plate were exposed to 3.5% NaCl solution (added dropwise to the precrack three times a day) for three

TABLE 11

RESISTANCE TO STRESS-CORROSION CRACKING OF CS19 PLATE EXPOSED TO 3-1/2% NaC1 SOLUTION BY ALTERNATE IMMERSION


			Stressed		(0.75") Dia. Shor s-Fabricated		Transverse C-Rings Heated 1 wk/100°C		
Thickness	S-No.	Temper	%Y.S.	F/N	Days to Fail	F/N	Days to Fail		
	30	0 mm x 960 mm	x 3050 mm (12"	x 38"	x 120") Ingot				
25.4 mm (1.0")	438560	H3E19	75	0/3	OK-160	0/3	OK-160		
			50	0/3	OK-160	0/3	OK-160		
	460	mm x 1520 mm	x 3800 mm (18"	x 60"	x 150") Ingot				
25.4 mm	446288	H3E19	75	0/3	OK-280	0/3	OK-280		
			50	0/3	OK-280	0/3	OK-280		
25.4 mm	446289	H1E48	75	0/3	OK-280	0/3	OK-280		
			50	0/3	OK-280	0/3	OK-280		


Note: (1) F/N denotes number of specimens failed over number of specimens exposed.


conditions: as-fabricated, heated one week at 100°C, and one week at 80°C. Pop-in was difficult to achieve because of the toughness of the CS19 alloy. Crack growth was monitored daily, and the results are graphically presented in Figures 1-3.


The extensive crack growth observed in the asfabricated condition (Fig. 1) was not unexpected as extensive
crack growth was previously observed for laboratory-fabricated
CS19 plate. (1) The curve for the as-fabricated condition
was similar to the curves for the heated material. Metallographic examination of crack tips revealed that the propagation
was by typical intergranular SCC. Figures 4 (100X) and 5
(500X) are representative and show the cracking at the crack
tip to be following grain boundaries which are outlined
discontinuously with precipitate. The greater amount of
grain boundary precipitate in CS19 accounts for the more
rapid crack growth observed in the as-fabricated condition
for CS19 compared to 5456. There was some concern that
cracking was possibly associated with aligned constituents;
however, this did not appear to be a factor.

Figures 6-8 contain fracture mechanics-type specimen results for a 25.4 mm H1E48 temper plate tested in the same three conditions. The similarity in crack growth to that of Figures 1-3 again illustrates the equivalent corrosion performance of the H3E19 and H1E48 tempers.










CS19-H3E19 DCB SPECIMEN IN AS-FABRICATED CONDITION


Illustrates cracking (far right) at the crack tip in T/2 plane.




Figure 5

ENLARGEMENT (500X) OF CRACKING AT THE CRACK TIP IN FIG. 4
Note outlining of grain boundaries with precipitate and
intergranular path of cracking.







The stressed tensile bar and C-ring test results again indicated that the likelihood of SCC initiation in CS19-H3E19 plate was no greater than in 5456-H117 plate, but tests with fracture mechanics-type specimens showed the propagation of SCC in the S-L orientation under extreme stress intensity to be more rapid in CS19. If this is considered to be a serious limitation, successful service performance of CS19 would be dependent upon avoiding high short-transverse tensile stresses.

Resistance to General Corrosion in Sea Water

To determine the general corrosion resistance in sea water, 6.3 mm and 25.4 mm thick CS19 alloy plates were tested in quiescent sea water as 102 mm x 305 mm (4" x 12") panels and in flowing sea water (610 mm/sec or 2 ft/sec) as 102 mm x 152 mm (4" x 6") panels. Because Alcoa Laboratories does not have facilities to perform these tests, the sea water tests were performed in the standard facilities maintained at Wrightsville Beach, North Carolina, by the International Nickel Company's Francis L. LaQue Corrosion Laboratory.

For both quiescent and flowing sea water, tests were also made for some of the other tempers included in the initial evaluation program and not just for the H3E19 temper plates.

Quiescent Sea Water. Table 12 shows the results of visual examinations of panels of as-fabricated plate from both large and small size ingot after 180 days' exposure totally immersed in sea water. The panels showed excellent resistance to corrosion for both thicknesses of plate with no attack or only minute blisters or pits observed. The results were similar to those previously observed for 25.4 mm laboratory-fabricated CS19 plate and 5456-H117 alloy plate in the test and exploratory development contract. (1) In this work, no appreciable corrosion was observed after 406 days' exposure for panels of CS19-type alloy compositions in the original series of materials evaluated.

Flowing Sea Water. A similar group of panels (Table 13) was exposed to flowing sea water (610 mm/sec or 2 ft/sec) for a period of 180 days. Visual examinations revealed excellent resistance to corrosion in the asfabricated condition with no significant attack of the surface or edges. The performance of the 25.4 mm thick CS19 plate was similar to that observed for the laboratory-fabricated CS19 and 5456-H117 alloy plate. (1)

As in the case of the quiescent sea water tests, the performance of CS19-H3E19 was at least comparable to that of 5456-H117 plate.

TABLE 12

RESISTANCE TO CORROSION OF CS19 PLATE AFTER 180 DAYS'
EXPOSURE TO QUIESCENT SEA WATER

Thickness	Temper	S-No.	As-Fabricated	After 7 Days at 100°C	Annealed
		300 mm x 960 mm	n x 3050 mm (12" x	38" x 120") Ingot	
6.3 mm	H1E48	438628	***	**	
(.250")	H2E38	448726	***	***	
	H3E19	438564	N	N	N
25.4 mm (1.0")	H3E19	438560	***	***	N
		460 mm x 1520 m	nm x 3800 mm (18" x	: 60" x 160") Ingot	
6.3 mm	H1E48	438568	***	**	
	H3E19	438567	N		N
25.4 mm	H1E48	438566	***	***	
	H3E19	438565	*	*	N

Notes: (1) 102 mm \times 305 mm (4" \times 12") panels were used.

- (2) Test made at Francis L. LaQue Corrosion Laboratory, Wrightsville Beach, N.C.
- (3) Code for visual examination:
 - N = no appreciable attack
 - * = A very few scattered mild pits on rolled surfaces
 - ** = A few scattered sites of minute blisters and pits on rolled surfaces
 - *** = Many scattered sites of minute pitting on rolled surfaces

TABLE 13

RESISTANCE TO CORROSION OF CS19 PLATE AFTER 180 DAYS'
EXPOSURE TO FLOWING SEA WATER

Thickness	Temper	S-No.	As-Fabricated	After 7 Days at 100°C	Annealed
		300 mm x 960 mm	x 3050 mm (12" x	38" x 120") Ingot	
6.3 mm	H1E48	438628	N	N	
(.250")	H2E38	448726	N	N	
	H3E19	438564	N	N	N
25.4 mm (1.0")	H3E19	438560	N	N	N
		460 mm x 1520 m	m x 3800 mm (18" ;	x 60" x 160") Ingot	
6.3 mm	H1E48	438568	N	N	
	H3E19	438567	N	N	N
25.4 mm	H1E48	438566	N	N	
	H3E19	438565	N	N	N

Notes: (1) 102 mm x 152 mm (4" x 6") panels were used.

- (2) Flow rate was 610 mm/sec (2 ft/sec).
- (3) Tests made at Francis L. LaQue Corrosion Laboratory, Wrightsville Beach, N.C.
- (4) Code for visual examination:
 N = no appreciable attack

After Elevated Temperature Exposure

To simulate the metallurgical changes that will be produced by long time natural aging during service, three thermal treatments were employed: one week at 100°C, one week at 80°C, and 30 days at 66°C. The more drastic treatment of one week at 100°C was used in most instances as it produces the more extreme degree of precipitation and its general usage is more commonly recognized.

Exfoliation Resistance

The results listed in Table 4 indicated that heating one week at 100°C did not affect the excellent resistance to exfoliation observed in the as-fabricated condition.

SCC Resistance

Long Transverse. The results contained in Table 10 demonstrated that stressed tensile bars and beam assemblies of material heated one week at 100°C were not adversely affected as no evidence of SCC was observed after an exposure period of 289 or 290 days.

Short Transverse. Table 11 shows that short transverse C-rings stressed to 75 and 50% of the long transverse yield strengths also maintained the same high resistance to SCC after heating as in the as-fabricated condition.

While these results were similar to the laboratory-fabricated CS19 plate and one lot of CS19-type composition evaluated in the test and exploratory development contract (1), a second lot in that program showed SCC similar to that of 5456-H117. Because of the limited number of comparative lots of both alloys tested to date, it can only be concluded that CS19 is showing some susceptibility to SCC but is not highly susceptible and therefore, it is not less resistant to SCC than 5456-H117 alloy plate.

Fracture Mechanics-Type Specimens. Extensive crack growth was observed for the double cantilever beam CS19 specimens after being heated one week at 100°C and one week at 80°C as graphically presented in Figures 2, 3, 7 and 8. The grain boundaries were almost continuously outlined with precipitate (Figure 9 at 100X and 10 at 500X) which resulted in intergranular SCC and a more rapid crack growth rate. This condition was also observed with heated 5456-H117 plate. (1)

Resistance to General Corrosion in Sea Water

Quiescent Sea Water. Panels of the 25.4 mm plate

(Table 12) showed excellent resistance to corrosion in sea

water in both the as-fabricated and heated conditions. In

the case of the thinner 6.3 mm plate, the H1E48 temper

heated one week at 100°C showed randomly scattered small

blisters on both top and bottom surfaces for both size ingots.




Figure 9

S-446233-SL4

100X

H3PO4 Etch

CS19-H3E19 DCB SPECIMENS, HEATED 7 DAYS AT 100°C Illustrates cracking (far right) at the crack tip in T/2 plane.




Figure 10

ENLARGEMENT (500X) OF CRACKING AT THE CRACK TIP IN FIG. 9

Note the nearly continuous outlining of grain boundaries with precipitate and resulting intergranular SCC.

This was not evident, however, in the as-fabricated condition nor with the thick plate. It should be noted that this material heated one week at 100°C when exposed to the accelerated exfoliation test (ASSET) showed no appreciable exfoliation attack (Table 4).

Flowing Sea Water. Heating one week at 100°C did not affect the excellent resistance to corrosion observed in the as-fabricated condition (Table 13).

CS19-0 Plate

Resistance to General Corrosion in Sea Water

The results of visual examinations of panels of annealed plate exposed to quiescent and flowing sea water for 180 days (Tables 12 and 13) indicated excellent resistance to corrosion for both thicknesses of plate.

CS19-H3E19 PLATE WELDMENTS

Weld properties initially were determined on ten items of plate in various tempers produced from two sizes of production size ingots (Tables 5 and 6). These were GMA (MIG) welded using CS19-type filler electrode. Welding parameters, unless otherwise noted, were standard butt welds using a 60°V, 180-220 amps, 26-28 volts and shielding gas of 40% helium-60% argon at 1.7 m³/hr (60 CFH).

An interpass cooling temperature of 120°C was employed initially in all tests to produce a desirable structure for minimizing susceptibility to SCC as had previously been demonstrated for 25.4 mm (1.0") CS19 plate. (1) Unsatisfactory SCC results on 6.3 mm (.250") plate led to a later investigation of other interpass cooling temperature and/or heating of 6.3 mm plate prior to welding in attempts to improve the weld/parent interface microstructure and SCC resistance.

The supply of CS19-type electrode was exhausted by the time the later investigations were started.

Commercial 5556 electrode was used since the SCC failures were associated with the heat-affected zone in the parent plate as discussed subsequently. Previous work in the earlier contract had indicated strengths of weldments were equivalent for the two electrode alloys and this was also indicated in limited comparisons in the current work.

Tensile Properties

As-Welded Condition

The results of tensile tests of reduced section CS19-H3E19 weld specimens (Fig. III in Appendix) produced with 5556 and CS19 electrode are presented in Table 14 along with full section weldment test results from Tables 5 and 6. Reduced section test results for plate fabricated from the two sizes of ingot were somewhat inconsistent because of porosity but indicated about equivalent contributions to the strength of the weldment for the two electrodes.

After Elevated Temperature Exposure

Results of tensile testing of full section specimens after heating for 7-30 days at 66°C, 80°C, or 100°C are listed in Table 15. The weld strengths show slight decreases after heating in this temperature range. Although such thermal treatments induce precipitation of the Al₃Mg₂ phase, they do not have a large effect on strengths, although such precipitation can have adverse effects on SCC performance, particularly in recrystallized material.

The initial strengths of the 25.4 mm CS19-H3E19 plate weldments were slightly lower than reported in Table 5 for this product and the subsequent loss in yield strength upon elevated temperature storage brought yield strength values close to or slightly below the target 30 ksi minimum values.

TABLE 14 REDUCED SECTION TENSILE STRENGTHS FOR CS19-H3E19 WELDMENTS PRODUCED WITH CS19-TYPE AND 5556 ELECTRODE

Thickness S-No. Ingot Size Electrode Section Specimens Section S						Full Se	ction :	Specimens	(Average) 1			
Thickness									Elongat	ion in	Redu	ced Section	n Specimens
6.3 mm (2.50") 438564 300 mm x 960 mm (12" x 38")					Tens	ile Str.	Yie:	ld Str.	50.8 mm	254 mm			
(.250")	Thickness	S-No.	Ingot Size	Electrode	MPa	(ksi)	MPa	(ksi)	(2")	(10")	MPa	(ksi)	Fracture ²
	6.3 mm	438564		CS19	348	(50.5)	265	(38.5)	7.8	3.7			TW
Avg. Size Avg. Avg. Size Avg.	(.250")		(12" x 38")										TW
Aug.											336	(48.8)	TW
Avg.										Avg.	317	(46.0)	
ABS67 460 mm x 1520 mm				5556									TW
Avg.											233	$(33.8)^3$	TW
438567 460 mm x 1520 mm (18" x 60") **CS19** 376** (54.6) 263** (38.1) 11.3											325	(47.1)	TW
18" x 60") 232										Avg.	310	(44.9)	
Avg. 271 (39.3) TW		438567	460 mm x 1520 mm	CS19	376	(54.6)	263	(38.1)	11.3	6.5	223	(32.3)3	TW
Avg. 271 (39.3) TW			(18" x 60")								232	$(33.7)^3$	TW
New Year Section Sec											271		TW
25.4 mm										Avg.			
25.4 mm 438560 300 mm x 960 mm CS19 356 (51.6) 219 (31.7) 11.2 6.4 305 (44.2) EWSTW (1.0")				5556							266	(38.6)	EW
Avg. 294 (42.6)											305	(44.3)	TW
25.4 mm 438560 300 mm x 960 mm CS19 356 (51.6) 219 (31.7) 11.2 6.4 305 (44.2) EWSTW (1.0")											309	(44.8)	TW
1.0" 336										Avg.	294	(42.6)	
1.0" 336	25.4 mm	438560	300 mm x 960 mm	CS19	356	(51.6)	219	(31.7)	11.2	6.4	305	(44.2)	EW&TW
338 (49.0) TW Avg. 326 (47.3) 5556 336 (48.7) EWSTW 330 (47.9) EW Avg. 333 (48.3) 438565 460 mm x 1520 mm CS19 354 (51.4) 219 (31.7) 13.2 7.4 283 (41.0) EWSTW 319 (46.3) EW 323 (46.9) EW Avg. 308 (44.7) 5556 333 (48.3) EWSTW 333 (48.3) TW 335 (48.6) TW											336		EW&TW
Avg. 326 (47.3) 5556 336 (48.7) EWSTW 330 (47.9) EW Avg. 333 (48.3) 438565 460 mm x 1520 mm CS19 354 (51.4) 219 (31.7) 13.2 7.4 283 (41.0) EWSTW 323 (46.9) EW Avg. 308 (44.7) 5556 333 (48.3) EWSTW 333 (48.3) TW 335 (48.6) TW													
5556 336 (48.7) EWSTW 330 (47.9) EW Avg. 333 (48.3) 438565 460 mm x 1520 mm CS19 354 (51.4) 219 (31.7) 13.2 7.4 283 (41.0) EWSTW 323 (46.9) EW Avg. 308 (44.7) 5556 333 (48.3) EWSTW 333 (48.3) TW 335 (48.6) TW										Avg.	326		
330 (47.9) EW Avg. 333 (48.3) 438565 460 mm x 1520 mm CS19 354 (51.4) 219 (31.7) 13.2 7.4 283 (41.0) EWSTW 319 (46.3) EW 323 (46.9) EW Avg. 308 (44.7) 5556 333 (48.3) EWSTW 335 (48.6) TW													
Avg. 333 (48.3) 438565 460 mm x 1520 mm CS19 354 (51.4) 219 (31.7) 13.2 7.4 283 (41.0) EWSTW 319 (46.3) EW 323 (46.9) EW Avg. 308 (44.7) 5556 333 (48.3) EWSTW 333 (48.3) TW 335 (48.6) TW				5556									
438565 460 mm x 1520 mm CS19 354 (51.4) 219 (31.7) 13.2 7.4 283 (41.0) EWSTW 319 (46.3) EW 323 (46.9) EW Avg. 308 (44.7) 5556 333 (48.3) EWSTW 335 (48.6) TW													EW
319 (46.3) EW 323 (46.9) EW Avg. 308 (44.7) 5556 333 (48.3) EWSTW 333 (48.3) TW 335 (48.6) TW										Avg.	333	(48.3)	
323 (46.9) EW Avg. 308 (44.7) 5556 333 (48.3) EWSTW 333 (48.3) TW 335 (48.6) TW		438565	460 mm x 1520 mm	CS19	354	(51.4)	219	(31.7)	13.2	7.4			
Avg. 308 (44.7) 5556 333 (48.3) EWSTW 333 (48.3) TW 335 (48.6) TW													
5556 333 (48.3) EWSTW 333 (48.3) TW 335 (48.6) TW													EW
333 (48.3) TW 335 (48.6) TW										Avg.	308	(44.7)	
335 (48.6) TW				5556									
												(48.3)	TW
Avg. 334 (48.4)											335	(48.6)	TW
										Avg.	334	(48.4)	

Notes: (1) Averages of three tests -- See Tables 5 and 6.
(2) TW is through centerline of weld; EW is edge of weld.
(3) Values disregarded in averages because of excessive porosity present.

TABLE 15

WELD STRENGTHS OF CS19-H3E19 PLATE WELDMENTS AFTER EXTENDED STORAGE AT ELEVATED TEMPERATURES

						As-	As-Welded				Aft	After 30 Days			
Thickness	S-No.	Ingot Size	Electrode	Tensi	MPa (ksi)	Yielo MPa	MPa (ksi)	Elong. 50.8 mm (2")	254 mm (10")	MPa	Tensile Str.	Yield Str.	-	Elong 50.8 mm (2")	254 mm (10")
6.3 mm (.250")	438564	300 mm × 960 mm (12" × 38")	CS19	411 407 412	(59.6) (59.0) (59.8)	281 286 287	(40.8) (41.5) (41.6)	11.0	5.2	379	(54.9) (60.5)	283	(41.1)	7.5	3.4
			Avg.	410	(59.5)	285	(41.3)	11.3	5.2	398	(57.7)	283	(41.1)	9.2	9.9
	438567	460 mm x 1520 mm (18" x 60")	CS19	319	(46.2)	269	(39.0)	6.5	2.1	414	(60.1)	265	(38.4)	14.5	9.5
			Avg.	372	(54.0)	272	(39.5)	11.0	2.8	392	(56.9)	266	(38.5)	12.3	7.8
25.4 mm	438560	300 mm x 960 mm	CS19	316	(45.9)	211	(30.5)	9.5	4.5	328	(47.6)	204	(29.6)	11.0	5.6
(1.0)				349	(50.6)	210	(30.4)	13.0	. 8.	302	(43.8)	204	(29.6)	9.5	4.4
			Avg.	331	(48.0)	210	(30.4)	11.5	5.9	325	(47.1)	204	(59.6)	11.2	5.8
	438565	460 mm x 1520 mm	CS19	356	(51.7)	214	(31.1)	15.3	8.6	346	(50.2)	212	(30.7)	13.0	7.2
				358	(51.9)	214	(31.1)	15.5	8.7	352	(51.0)	211	(30.6)	13.5	0.8
			Avg.	356	(51.7)	214	(31.1)	15.3	8.6	353	(51.2)	211	(30.6)	13.2	7.8
					Aft	After 7 D	Days at	2,08			Aft	After 7 D	Days at]	100°C	
6.3 mm	438564	300 mm x 960 mm	CS19	415	(60.2)	284	(41.2)	11.0	5.5	407	(59.4)	280	(40.7)	11.0	5.2
(.250")				423	(61.3)	288	(41.7)	12.0	6.3	423	(61.3)	281	(40.8)	12.0	5.5
			Avg.	414	(60.5)	288	(41.5)	11.3	5.8	414	(60.0)	287	(40.9)	11.2	5.0
	438567	460 mm x 1520 mm	CS19	404	(58.6)	266	(38.6)	13.5	8.6	412	(8.65)	263	(38.1)	13.0	0.6
				418	(9.09)	268	(38.9)	15.5	10.6	417	(60.5)	262	(38.0)	14.5	9.6
			Avg.	407	(59.1)	263	(38.1)	14.8	9.6	404	(58.6)	263	(38.1)	12.7	8.5
25.4 mm	438560	300 mm x 960 mm	CS19	339	(49.1)	206	(29.8)	11.5	6.7	404	(90.09)	202	(29.3)	12.0	7.1
(1.0")				330	(47.8)	205	(29.7)	11.5	7.3	331	(48.0)	201	(29.2)	11.0	7.6
			Avg.	340	(49.3)	205	(29.7)	11.8	6.7	344	(49.9)	201	(29.2)	11.8	6.9
	438565	460 mm x 1520 mm	CS19	336	(48.7)	208	(30.2)	13.0	7.5	347	(50.3)	205	(29.7)	14.0	6.8
				344	(49.9)	208	(30.2)	13.0	7.5	403	(50.5)	207	(30.0)	15.5	9.5
				351	(20.9)	500	(30.3)	13.5	8.7	331	(48.0)	207	(30.0)	12.5	7.0
			Avg.	343	(49.8)	208	(30.2)	13.2	7.9	342	(49.6)	206	(59.9)	14.0	8.4

Note: MIG welds with 120°C interpass cooling temperature.

Fracture Toughness

In a manner similar to fracture toughness testing of the parent plate, CS19-H3E19 plate weldments were tested across the weld using specimens with the notch located in the weld bead. For 6.3 mm plate, double-notched sheet specimens (Fig. IV in Appendix) were employed while notched, round specimens were used for 25.4 mm plate.

Prior fracture toughness tests of 25.4 mm plate weldments in the test and development contract indicated CS19-H1E48 and 5456-H117 MIG weldments with Al-7Mg-0.1Ti electrode alloy had similar fracture toughness characteristics. (1) Current notch-tensile test results listed in Table 16 for 25.4 mm CS19-H3E19 plate MIG welded with CS19-type electrode show notch-tensile strength/yield strength (NTS/YS) values of about 1.7 compared to 1.8 for the H1E48 plate weldments in the earlier work. There is some implied advantage to weld toughness with the use of CS19 electrode.

The fracture toughness of the 6.3 mm plate weldments as measured by notch-tensile/yield strength ratios is considerably lower than that of 25.4 mm plate and is probably a reflection of the poor weld quality experienced with the 6.3 mm plate weldments as well as of the higher strength and lower ductility of the thinner parent plate.

TABLE 16 NOTCH-TENSILE TEST RESULTS FOR CS19-H3E19 PLATE WELDMENTS $^{\mathrm{l}}$

Thickness	Ingot Size	S-No.	Electrode	Notch-Te	(ksi)	Yiel MPa	d Str. ² (ksi)	NTS/YS
6.4 mm (.250")	300 mm x 960 mm (12" x 38")	438564	CS19	261 259 261	(37.8) (37.5) (37.9)	267 266	(38.7) (38.6)	.98 .97
			Avg.	260	(37.7)	264 265	(38.3)	.98
			5556	239 239 247	(34.6) (34.6) (35.8)			
			Avg.	241	(35.0)			
	460 mm x 1520 mm (18" x 60")	438567	CS19	257 255 256	(37.3) (37.0) (37.2)	260 263 265	(37.7) (38.1) (38.4)	.99 .97
			Avg.	256	(37.2)	263	(38.1)	.98
			5556	240 232 248	(35.8) (33.6) (36.0)			
			Avg.	242	(35.1)			
25.4 mm (1.0")	300 mm x 960 mm	438560	CS19	361 362 366	(52.3) (52.5) (53.1)	220 219 218	(31.8) (31.7) (31.6)	1.64 1.66 1.65
			Avg.	363	(52.6)	219	(31.7)	1.66
			5556	361 358	(52.3) (51.9)			
			Avg.	358 359	(51.9) (52.0)			
	460 mm x 1520 mm	438565	CS19	365 385	(52.9) (55.9)	219 218	(31.7) (31.6)	1.65 1.75
			Avg.	379 376	(54.8) (54.5)	220 219	(31.9) (31.7)	1.70 1.70
			5556	346 353	(50.2) (51.2)			
			Avg.	348 349	(50.5) (50.6)			

Notes: (1) MIG weld with 120°C interpass cooling temperature.
(2) Full section weldment yield strength from Tables 5 and 6.

Weld Ductility

Weld ductility as measured by free-bend specimens (Fig. V and VI in the Appendix) are presented in Table 17. Guided face, guided root, or free bend specimens are an added measure of determining weld soundness by determining their ability to bend satisfactorily over a bend radius without fracture or developing cracks or other open defects during bending without such defects exceeding a specified size after bending. The results show that 25.4 mm CS19-H3E19 plate weldments are quite ductile, are identical for both 5556 and CS19 electrodes, and are similar to those of 5456-H117 commercial plate weldments.

For 6.3 mm CS19-H3E19 plate weldments, weld ductility results were somewhat erratic which is attributed to the inconsistency in weld quality. Where 180° bends were obtained, the weld ductility was comparable to that of weldments of 1.0" CS19-H3E19 plate and to 5456-H117 commercial plate weldments.

Corrosion Resistance of CS19 Weldments

The weldments of CS19-H3E19 plate were subjected to the same types of corrosion evaluation as the parent plate, i.e., exfoliation and stress-corrosion susceptibility in accelerated tests and general corrosion in quiescent and flowing sea water. Evaluations were made of the as-welded plate and after exposure to elevated temperatures.

TABLE 17 GUIDED BEND TESTS OF CS19-H3E19 PLATE WELDMENTS

				Gu	ided Root I	Bend	Gu	ided Face I	Bend
					Angle,			Angle,	
Thickness	Ingot Size	S-No.	Electrode	Radius	Degrees	Remarks	Radius	Degrees	Remarks
6.3 mm	300 mm x 960 mm	438564	CS19	4T	180	OK	4T	180	F-EW
(.250")	(12" x 38")			4T	180	OK	4T	180	OK
				4T	180	OK	4T	180	OK
			5556	4T	180	OK	4T	100	F-EW
				4T	180	OK	4T	180	F-EW
				4T	95	F-TW	4T	100	F-EW
	460 mm x 1520 mm	438567	CS19	4T	180	OK	4T	180	OK
	(18" x 60")			4T	180	OK	4T	180	OK
				4T	95	F-EW	4T	180	OK
			5556	4T	180	OK	4T	180	OK
				4T	180	OK	4T	180	OK
				4T	140	F-EW	4T	180	OK
25.4 mm	300 mm x 960 mm	438560	CS19	3-1/2T	180	OK	3-1/2T	180	OK
(1.0")				3-1/2T	180	OK	3-1/2T	180	OK
			5556	3-1/2T	180	OK	3-1/2T	180	OK
				3-1/2T	180	OK	3-1/2T	180	OK
				3-1/2T	180	OK	3-1/2T	180	OK
	460 mm x 1520 mm	438565	CS19	3-1/2T	180	OK	3-1/2T	180	OK.
	100 111 11 2000 1101		0025	3-1/2T	180	OK	3-1/2T	180	OK
				3-1/2T	180	OK	3-1/2T	180	OK
			5556	3-1/2T	180	OK	3-1/2T	180	ок
				3-1/2T	180	OK	3-1/2T	180	OK
				3-1/2T	180	OK	3-1/2T	180	OK

Notes: (1) MIG as-welded, 120°C interpass cooling.
(2) EW - Edge of weld failures.
(3) TW - Through the weld failures.

As-Welded Condition

Exfoliation Resistance

Butt-welded strip specimens, 38 mm x 203 mm (1-1/2" x 8") from two lots each of 6.3 mm and 25.4 mm thick CS19-H3E19 plate welded with CS19 filler wire were exposed to ASSET to determine their resistance to exfoliation. The results presented in Table 18 for as-welded and heated specimens showed no evidence of exfoliation for the as-welded specimens.

SCC Resistance

For stress-corrosion testing, full thickness beam specimens 25.4 mm wide x 508 mm long (1" x 20") with machined edges and weld beads intact were stressed to 75% of the weldment yield strength and exposed to the 3-1/2% NaCl alternate immersion test. A stressed beam assembly and the stressing formula are shown in Figure VII of the Appendix. In the loading procedure it was assumed that the beams had a uniform thickness and were straight, thus neglecting any effect of bow in the joint or of stress concentrations in the fillets at the edges of the weld beads.

Beam assemblies of plant-fabricated 6.3 mm and 25.4 mm thick CS19-H3E19 plate showed no evidence of SCC in the as-welded condition after an exposure of 188 days (Table 19) which is again indicative of the good resistance to SCC reported for the 25.4 mm thick laboratory-fabricated

TABLE 18

RESISTANCE TO EXPOLIATION OF CS19 WELDMENTS

AFTER EXPOSURE TO ASSET¹ TEST

Thickness	Temper	S-No.	Filler Alloy	-1 As-Welded	-2 Heated 7 Days/100°C	-3 Heated 7 Days/80°C	-4 Heated 30 Days/66°C
			300 mm x	960 mm x 3050	mm (12" x 38" x 120")	Ingot	
6.3 mm (.250")	H3E19	438564	CS19	N	N	N	N
25.4 mm (1.000")	H3E19	438560	CS19	N	N	N	N
			460 mm x	1520 mm x 380	0 mm (18" x 60" x 150")	Ingot	
6.3 mm	H3E19	438567	CS19	N	E-B	N .	N
25.4 mm	H3E19	438565	CS19	N	N	N	N

Note: (1) 24 hours total immersion in solution of lN NH₄Cl, 0.25 N NH₄NO₃, 0.01M ammonium tartrate and 3 g/l hydrogen peroxide at 66°C; N is no appreciable attack; E is exfoliation attack with degree of severity from A to D.

TABLE 19

RESISTANCE TO STRESS-CORROSION CRACKING OF CS19 WELDMENTS EXPOSED AS STRESSED BEAM ASSEMBLIES TO 3-1/2% NaCl SOLUTION BY ALTERNATE IMMERSION

					Be	eam Ass	semblies - Stres	sed 7	5% Weldment Y.S.		
			Filler		As-Welded	Heate	ed 7 Days/100°C	Heate	ed 7 Days/80°C	Heate	ed 30 Days/66°C
Thickness	Temper	S-No.	Alloy	F/N1	Days to Fail	F/N	Days to Fail	F/N	Days to Fail	F/N	Days to Fail
			300 mm	× 960 r	mm x 3050 mm (1.	2" x 3	B" x 120") Ingot				
6.3 mm (.250")	H3E19	438564	CS19	0/2	OK-188	2/2	4,4	0/2	OK-188	2/2	4,9
25.4 mm (1.000")	H3E19	438560	CS19	0/2	OK-188	0/2	OK-188	0/2	OK-188	0/2	OK-188
			460 mm	x 1520	mm x 3800 mm (18" x	50" x 150") Ingo	t			
6.3 mm	H3E19	438567	CS19	0/2	OK-188	2/2	7,7	0/2	OK-188	1/2	7, OK-188
25.4 mm	H3E19	438565	CS19	0/2	OK-188	0/2	OK-188	0/2	OK-188	0/2	OK-188

Note: (1) F/N designates number of specimens failed over number of specimens exposed.

CS19 plate in the test and exploratory contract. (1) In the latter, no SCC failures in the as-welded beam assemblies of CS19-H1E48 plate occurred in exposures up to 365 days.

Resistance to General Corrosion in Sea Water

Quiescent Sea Water. Table 20 lists results of
examinations of weldments of CS19-H3E19 alloy after 180
days' immersion in quiescent sea water. The panels showed
excellent resistance to corrosion with no indication of
any special attack of the weld zone or in the edges of the
plate. The performance was similar to that observed for
laboratory-fabricated 5456 and CS19 plate in the test and
exploratory contract work.

Flowing Sea Water. A similar group of panels (Table 21) was exposed to flowing sea water for a period of six months. Visual examinations revealed excellent resistance to corrosion. As in the case of the quiescent sea water tests, the performance of plant-fabricated CS19-H3E19 plate was comparable to that of laboratory-fabricated 5456 and CS19 plate in the earlier work.

After Elevated Temperature Exposure

As in the case of parent plate, butt-welded strip specimens were heated at the various times and temperatures—one week/100°C, one week/80°C, and 30 days/66°C—to simulate the various metallurgical changes that might be expected to occur in service.

TABLE 20

RESISTANCE TO CORROSION OF CS19-H3E19 WELDMENTS 1 AFTER 180 DAYS'
EXPOSURE TO QUIESCENT SEA WATER

Thickness	S-No.	-1 As-Welded	-2 7 Days/100°C	-3 7 Days/80°C	-4 30 Days/66°C
	300 mm x	960 mm x 3050 m	um (12" x 38" x 120	") Ingot	
6.3 mm (.250")	438564	N	*	N	N
25.4 mm (1.0")	438560	N	N	N	N
	460 mm >	1520 mm x 3800) mm (18" x 60" x 3	150") Ingot	
6.3 mm	438567	N	*	N	N
25.4 mm	438565	N	N	N	N

Notes: (1) Flow rate was 610 mm/sec (2 ft/sec). CS19 alloy filler wire

(2) Code for visual examination: N = No appreciable attack

* = A few scattered sites of minute blisters
 and pits on rolled surfaces.

TABLE 21

RESISTANCE TO CORROSION OF CS19-H3E19 WELDMENTS AFTER 180 DAYS EXPOSURE TO FLOWING SEA WATER

Thickness	S-No.	-1 As-Welded	-2 7 Days/100°C	-3 7 Days/80°C	-4 30 Days/66°C
	300 mm x	960 mm x 3050 mm	(12" x 38" x 12	20") Ingot	
6.3 mm (.250")	438564	N	N	N	N
25.4 mm (1.0")	438560	N	N	N	N
	460 mm x	1520 mm x 3800 m	m (18" x 60" x 1	L50") Ingot	
6.3 mm	438567	N	N	N	N
25.4 mm	438565	N	N	N	N

Notes: (1) Flow rate was 610 mm/sec (2 ft/sec). CS19 alloy filler wire

(2) Code for visual examination: N = No appreciable attack

6.3 nm (.250") Thick CS19-H3E19 Plate Welded with CS19 Filler Exposed to ASSET for 24 Hours Note 3 nm to 6 mm wide band of exfoliation on each side of -2 specimen (see arrows). Figure 11

Exfoliation Resistance

The results listed in Table 18 showed exfoliation of only one specimen. This was the 6.3 mm CS19-H3E19 welded plate specimen from the 460 mm x 1520 mm (18" x 60") ingot heated one week/100°C (-2 of Fig. 11) which exfoliated at the heat-affected zone in a narrow band approximately 6.3 mm (0.250") in width. Although the 6.3 mm thick CS19-H3E19 weldment from the 300 mm x 960 mm (12" x 38") ingot did not show any significant attack, there is no reason to believe the difference in performance is related to ingot thickness. This form of exfoliation at the heat-affected zone has been occasionally observed with thin 5456-H117 butt welds so that the performance of 6.3 mm thick CS19 alloy weldments is not completely unexpected.

SCC Resistance

Improved welding procedures were developed with the laboratory-fabricated CS19 plate for the test and exploratory development contract to overcome susceptibility to SCC initially encountered in the 25.4 mm thick plate. (1) As indicated in Table 19, plant-fabricated plate of the same thickness welded by the same procedures showed no SCC failures after a significant exposure period of 188 days in the 3-1/2% NaC1 alternate immersion test when subjected to all three thermal treatments.

These welding procedures, however, were not effective with the 6.3 mm thick plate as SCC failures occurred in relatively short periods of time, four to nine days, for weldment specimens heated one week at 100°C and 30 days at 66°C. No failures, however, were observed with specimens heated for one week at 80°C.

Several of the failures were examined metallographically to determine the cause of failure. Figures 12 through 15 are photomicrographs of the 6.3 mm thick CS19-H3E19 weld specimen, S-438564-7, heated one week at 100°C, which failed after four days' exposure to the 3-1/2% NaCl solution by alternate immersion and is representative of the failures that occurred. Figure 12 shows the crack initiating at the toe of the weld and proceeding through the heat-affected zone in close proximity to the weld interface. Figure 13 is an enlargement (500X) of the initiation of the crack at the toe of the weld (Figure 12), and Figure 14 is an enlargement of the tip of the crack beyond that shown in Figure 12. Both figures indicate that the structure in the heataffected zone is recrystallized and that the grain boundaries are continuously outlined with precipitate, thus providing the intergranular path for the SCC failures. These structures can be compared with the microstructures shown in Figure 15 which is parent plate away from the heat-affected zone. The grain structure is more elongated for the parent plate and shows less continuity of precipitate.




Figure 12

S-438564-7

50X

H3PO4 Etch

6.3 mm (.250") CS19-H3E19 welded with CS19, 120°C interpass cooling; heated 7 days/100°C. Illustrates SCC cracking at heat-affected zone (HAZ).




Figure 13

S-433564-7

500X

H3PO4 Etch

Enlargement of Fig. 12 at toe of weld, shows initiation of cracking in recrystallized grain structure of HAZ.




Figure 14

S-438564-7

500X

H₃PO₄ Etch

Enlargement of specimen of Fig. 12 at tip of crack showing intergranular path of SCC failures. Grain boundaries of recrystallized structure continuously outlined with ${\rm Al}_3{\rm Mg}_2$ precipitate.



Figure 15

S-438564-7

500X

HgPO, Etch

6.3 mm (.250") CS19-H3E19 heated 7 days/100°C. Represents microstructure of parent plate remote from weld.

A study was initiated to improve the structure in the heat-affected zone employing various welding procedures, but no improvement was observed in metallographic studies of these weldments so SCC tests were not made.

Procedures employed in these attempts to improve the stress-corrosion cracking susceptibility were designed to change the precipitation pattern from one of highly selective precipitation on grain boundaries to a more general type and thus to reduce the readily available paths on which SCC might progress.

Changes in welding parameters were designed to slow down the cooling rate from the welding passes in order to permit a greater amount of precipitation to occur throughout the grain matrix. The changed welding parameters were the absence of cooling back-up plates, the placement of heat-sinks in the form of thick steel plates in areas adjacent to the weld bead during welding, and welds made with one pass (rather than three) to increase the heat of welding. None of the above procedures decreased the cooling rate sufficiently to improve the precipitation pattern from that obtained by the normal welding procedures.

The second program aimed at obtaining a more satisfactory microstructure in weldments of 6.3 mm plate involved both H3E19 and H2E38 temper plate given precipitation treatments of four hours at 232°C or one hour at 316°C to

obtain a dense Al₃Mg₂ precipitate structure throughout the grains at the expense of slight decreases in strength. The weldments were also made with and without controlled interpass cooling at 120°C. The results of the SCC tests were not favorable (Table 22). Failures occurred in a relatively short period of time of four to eighteen days for all of the assemblies heated one week at 100°C. Table 23 contains the tensile test results for the thermallytreated plate illustrating the loss in strength with these treatments.

Resistance to General Corrosion in Sea Water

Quiescent Sea Water. The majority of the heated

weldments (Table 20) showed no appreciable attack after six

months' exposure to quiescent sea water. Two of the

weldments in the H3E19 temper of the 6.3 mm thick plate

developed a few scattered sites of minute blisters and

pits on the rolled surfaces. Overall, the heated weldments

showed excellent resistance to corrosion in sea water.

Flowing Sea Water. All of the heated weldments (Table 21) showed no appreciable attack after six months' exposure to the flowing sea water.

TABLE 22

RESISTANCE TO SCC OF 6.3 mm (0.250") CS19 WELDMENTS HEATED 7 DAYS AT 100°C AND EXPOSED AS STRESSED BEAM ASSEMBLIES TO 3-1/2% NaC1 SOLUTION BY ALTERNATE IMMERSION

			Precipitation	Interpass Cooling		Assemblies -
S-No.	Temper	Ingot Thickness	Treatment	Temperature	F/N	Days to Fail
448726-2	H2E38	300 mm (12")	4 hr/232°C		2/2	6,6
438564-3	H3E19	300 mm (12")	4 hr/232°C		2/2	5,6
438567-1	H3E19	460 mm (18")	4 hr/232°C		2/2	4,5
448726-5	H2E38	300 mm	1 hr/316°C	40.042	2/2	4,4
438564-6	H3E19	300 mm	1 hr/316°C		2/2	6,6
438567-4	H3E19	460 mm	1 hr/316°C		2/2	5,6
448726-B	H2E38	300 mm	4 hr/232°C	120°C	2/2	6,11
438564-C	H3E19	300 mm	4 hr/232°C	120°C	2/2	4,6
438567-A	H3E19	460 mm	4 hr/232°C	120°C	2/2	6,13
448726-E	H2E38	300 mm	1 hr/316°C	120°C	2/2	4,5
438564-F	H3E19	300 mm	1 hr/316°C	120°C	2/2	17,18
438567-D	H3E19	460 mm	1 hr/316°C	120°C	2/2	13,22

Note: (1) 5556 alloy filler wire employed for all welds.

TABLE 23

TENSILE TEST RESULTS FOR WELDMENTS OF 6.3 mm (.250") CS19 PLATE GIVEN PRECIPITATION TREATMENTS AT 232°C AND 316°C

						As-Welde	ed Ten	sile Pro	perties	Ten	sile Pro	perti	es After	7 Days/100°C
Plate	Interpass			Ingot	Tens	ile Str.	Yiel	d Str.	Elongation,	Tens	ile Str.	Yiel	d Str.	Elongation,
Treatment	Cool	Temper	S-No.	Thickness	MPa	(ksi)	MPa	(ksi)	% in 50.8 mm	MPa	(ksi)	MPa	(ksi)	% in 50.8 mm
4 hr/232°C		H2E38	448726	300 mm (12")	319	(46.2)	230	(33.3)	6.5	335	(48.6)	227	(32.9)	8.0
		H3E19	438564	300 mm	343	(49.8)	243	(35.2)	8.0	321	(46.6)	243	(35.2)	6.0
			448567	460 mm (18")	288	(41.8)	225	(32.7)	6.5	400	(58.0)	229	(33.2)	13.0
1 hr/316°C		H2E38	448726	300 mm	327	(47.4)	228	(33.0)	8.0	352	(51.1)	223	(32.3)	9.5
		H3E19	438564	300 mm	299	(43.4)	236	(34.3)	7.5	248	(35.9)	230	(33.4)	4.0
			448567	460 mm	373	(54.1)	213	(31.0)	15.5	360	(52.2)	212	(30.7)	13.5
4 hr/232°C	120°C	H2E38	448726	300 mm	272	(39.5)	214	(32.8)	5.0	372	(54.0)	228	(33.0)	9.5
		H3E19	438564	300 mm	354	(51.4)	243	(35.2)	8.0	371	(53.9)	241	(34.9)	8.0
			448567	460 mm	350	(50.7)	226	(32.8)	10.5	315	(45.7)	228	(33.1)	6.0
1 hr/316°C	120°C	H2E38	448726	300 mm	321	(46.6)	225	(32.7)	7.5	357	(51.8)	225	(32.7)	5.7
		H3E19	438564	300 mm	290	(42.0)	232	(33.7)	6.5	310	(45.0)	229	(33,2)	6.0
			448567	460 mm	284	(41.2)	212	(30.8)	8.0	336	(48.7)	212	(30.8)	10.0

Note: (1) Tensile properties determined on full-thickness specimens.

SUMMARY

The primary objective of this contract was to determine the feasibility of rolling production size CS19 ingots on plant production rolling mills. Successful rolling of CS19 plate at Davenport Works without undue difficulty indicated that this alloy can be rolled commercially.

It was further indicated that CS19 plate produced by similar practices on laboratory equipment or on production mills had similar properties despite differences in the starting size of the ingots used.

Based on the initial screening evaluation which indicated the H1E48 and H3E19 tempers had the same strength and corrosion characteristics, it was decided to concentrate the complete testing program on the H3E19 temper which was the more advantageous temper from a production standpoint. The results of the more extensive tests, however, indicated some disadvantages to this temper compared to H1E48 temper; these were, first, a small loss in yield strength of H3E19 plate and possibly weldments after extended exposure to elevated temperatures and, secondly, a slightly lower aswelded yield strength in 25.4 mm (1.0") plate weldments by about 7-15 MPa (1-2 ksi). It should be noted that these observations are based on limited data but can be related to differences in the fabricating procedures employed for these

tempers. The 25.4 mm H3E19 plate obtained a higher proportion of its strength from cold working by a 4% stretch so a greater loss in strength could be anticipated by recovery in subsequent low temperature thermal treatments or from the heat of welding. No differences in corrosion characteristics were seen between H3E19 and H1E48 plate or weldments.

The production-rolled 25.4 mm plate demonstrated the same good corrosion characteristics of the 25.4 mm laboratory-rolled CS19-H1E48 plate and weldments in the previous test and exploratory development program.

Resistance to SCC for 6.3 mm (.250") plate weldments was good in the as-welded condition, but exposure to elevated temperatures simulating the effects of long time service made the weldments susceptible in accelerated SCC tests. In the previous test and exploratory development contract, weldments of 6.3 mm laboratory-rolled plate were not evaluated so that this situation had not been encountered previously.

The greater susceptibility to SCC of weldments of the thinner plate was attributed to its greater level of strain which was manifested in strength and toughness evaluations also. The heat of welding as a consequence produced a band of fine recrystallized grains adjacent to the fusion line, and these provided a path for SCC after

precipitation of ${\rm Al}_3{\rm Mg}_2$ at grain boundaries during the elevated temperature treatments. Attempts to overcome this susceptibility were limited by the expiration of the time and funds for the contract and were not successful.

CONCLUSIONS

The major conclusion to be drawn from work done for this contract was that the rolling of CS19 plate on production rolling mills from production-size ingots is feasible. No effect of ingot size on the properties or characteristics of the plate products was observed.

The conclusions of the previous test and exploratory contract were to the effect that CS19 plate met its requirements, i.e., a work-hardenable aluminum alloy plate material which has an as-welded minimum tensile yield strength of 207 MPa (30 ksi) and corrosion and fracture toughness properties equivalent to or better than those of the present 5456-H116 or H117 alloys, except for mechanically-precracked specimens in the asfabricated condition where CS19 showed more rapid SCC growth. Current work with production-rolled plate generally supports those conclusions except for one problem area which is the susceptibility to SCC of weldments of thin 6.3 mm CS19-H3E19 plate after exposure for extended periods to elevated temperatures to simulate the effects of long service times.

Further development work is needed in the following areas for the advancement of CS19 plate as a ship structure material: (1) development of fabricating and/or welding practices to overcome the susceptibility to SCC of

thin 6.3 mm (.250") CS19 plate weldments after extended exposure to elevated temperatures; and (2) development of production mill fabricating practices over the complete range of thicknesses and widths for ship structure applications to produce transverse hot-rolled yield strengths of at least 228 MPa (33 ksi) with a minimum of stretching. This will assure meeting the 207 MPa minimum as-welded yield strength both initially and after extended exposure to elevated temperatures simulating the effects of long time service. Complete characterization of all structural and corrosion properties to provide design allowables for CS19 would be a corollary of this work.

REFERENCES

- Rogers, R. W., Vernam, W. D. and Shumaker, M. B.;
 "Test and Exploratory Development of an Optimum
 Aluminum Alloy System for Ship Structures,"
 Naval Ship Systems Command Contract N00024-72-C-5571,
 July 23, 1974.
- 2. "Proposal to Explore the Feasibility of Production Rolling an Optimum Alloy System Which Has an As-Welded Yield Strength of 30 ksi Minimum," Aluminum Company of America, April 27, 1973.
- 3. Kaufman, J. G. and Holt, M.; "Fracture Characteristics of Aluminum Alloys," Alcoa Research Laboratories Technical Paper No. 18, 1965.

APPENDIX





Figure I - Full section weldment tensile specimen - 6.3 mm.



*NOTE: IF STOCK THICKNESS IS INSUFFICIENT FOR 2.4" BEAM HEIGHT, THIS DIMENSION MAY BE REDUCED

Figure II - Typical configuration of double cantilever beam specimen for stress-corrosion testing in short transverse direction (S-L orientation).




Figure III - Reduced section beam specimen for stress-corrosion cracking (flat).




Figure IV - Double-notched beam specimen for stress-corrosion cracking - 6.3 mm.




Figure V - Free bend specimen - guided face bend.





Figure VI - Free bend specimen - guided root bend.



Specie	Specimen dimensions for various plate thicknesses, inches	ensions	for vari	rious
+1	ol	ام	1	S
1/8	4	2	0	12
1/4	4	2	0	12
3/8	43/4	31/2	13	5
1/2	43/4	31/2	13	15
3/4	51/2	9	17	6
_	9	80	50	22
11/2	61/2	12	25	27

stressing		J
for	7	-
pinia	N	3 Et
Form		-
0	-	0 0

Where Δd = deflection, inch :f = nominal stress, psi E = Young's modulus, psi

Figure VII - Beam assembly for stress-corrosion testing of weldments.

Security Classification DOCUMENT CONTROL DATA - R&D (Security classification of title, body of abatract and indexing annotation must be entered when the overall report is classified) ORIGINATING ACTIVITY (Corporate author) 24. REPORT SECURITY CLASSIFICATION Aluminum Company of America Unclassified Alcoa Laboratories 26 GROUP Alcoa Center, Pennsylvania 15069 REPORT TITLE Exploration of Feasibility of Production Rolling an Optimum Aluminum Alloy System Which Has an As-Welded Yield Strength of 30 ksi Minimum. DESCRIPTIVE NOTES (Type of papert and inclusive detea) Final Dechnical Report, - 1/22/74-7/22/76 AUTHOR(S) (Last name, firet name, initiat) Regers, Ralph W., Jr./Pag Vernam, William D. Nersland Shumaker M. Byron / Shumaker 6 REPORT DATE TA TOTAL NO OF PAGES 76. NO OF REFS 9/22/76 BE CONTRACT OR GRAN SE ORIGINATOR'S REPORT NUMBER(5) N00024-74-C-5241 56-AC227 5. PROJECT NO SF541-702 Task 17350-21 OTHER REPORT NO(S) (Any other numbers that may be assigned this report) 10. A VAIL ABILITY/LIMITATION NOTICES 12 SPONSORING MILITARY ACTIVITY 11. SUPPLEMENTARY NOTES Naval Sea Systems Command (.250 - In.) Department of the Navy Washington, D.C. 20360 13 ABSTRACT A high-strength weldable Al-Mg alloy, CS19, was fabricated into plate from large ingots on production folling mills to evaluate feasibility. Plate in 6.3 mm (.250") and 25.4 mm (1.0") thicknesses was produced from two commercial sizes of ingot with no difference in product characteristics observed between plates fabricated from either size ingot. Tests on 25.4 mm thick CS19 plate and weldments showed it to have as-welded minimum yield strength of 207 MPa (30 ksi) and corrosion and fracture toughness equivalent to or better than 5456-H116 or H117 alloys. CS19 plate was shown to have more rapid rate of stress-corrosion crack growth than 5456 under some conditions but equal resistance to SCC initiation. The thinner plate and weldments had higher strength but lower toughness which was equivalent to that of 5456 of the same thickness. SCC resistance of the thinner plate and weldments was also good except for SCC resistance of weldments after thermal treatments simulating long service times. Greater strain in thinner plate produced an HAZ structure susceptible to SCC after thermal treatment.

DD . FORM 1473

Security Classification

017460

Security Classification

4	LINKA		LINK B		LINKC	
KEY WORDS	ROLE	WT	ROLE	WT	ROLE	WT
Aluminum-magnesium alloy (CS19, Experimental)						
High-strength, weldable aluminum alloy			1			
Aluminum alloy for ship structure						

INSTRUCTIONS

- ORIGINATING ACTIVITY: Enter the name and address of the contractor, subcontractor, grantee. Department of Defense activity or other organization (corporate author) issuing the report.
- 2a. REPORT SECURITY CLASSIFICATION: Enter the overall security classification of the report. Indicate whether "Restricted Data" is included. Marking is to be in accordance with appropriate security regulations.
- 2b. GROUP: Automatic downgrading is specified in DoD Directive 5200.10 and Armed Forces Industrial Manual. Enter the group number. Also, when applicable, show that optional markings have been used for Group 3 and Group 4 as authorized.
- 3. REPORT TITLE: Enter the complete report title in all capital letters. Titles in all cases should be unclassified. If a meaningful title cannot be selected without classification, show title classification in all capitals in parenthesis immediately following the title.
- 4. DESCRIPTIVE NOTES: If appropriate, enter the type of report, e.g., interim, progress, summary, annual, or final. Give the inclusive dates when a specific reporting period is covered.
- 5. AUTHOR(S): Enter the name(s) of author(s) as shown on or in the report. Enter last name, first name, middle initial. If military, show rank and branch of service. The name of the principal aithor is an absolute minimum requirement.
- REPORT DATE: Enter the date of the report as day, month, year, or month, year. If more than one date appears on the report, use date of publication.
- 7a. TOTAL NUMBER OF PAGES: The total page count should follow normal pagination procedures, i.e., enter the number of pages containing information.
- 7b. NUMBER OF REFERENCES: Enter the total number of references cited in the report.
- 8a. CONTRACT OR GRANT NUMBER: It appropriate, enter the applicable number of the contract or grant under which the report was written.
- 8b, 8c, & 8d. PROJECT NUMBER: Enter the appropriate military department identification, such as project number, subproject number, system numbers, task number, etc.
- 9a. ORIGINATOR'S REPORT NUMBER(S): Enter the official report number by which the document will be identified and controlled by the originating activity. This number must be unique to this report.
- 9b. OTHER REPORT NUMBER(S): If the report has been assigned any other report numbers (either by the originator or by the sponsor), also enter this number(s).
- 10. AVAILABILITY/LIMITATION NOTICES: Enter any limitations on further dissemination of the report, other than those

imposed by security classification, using standard statements such as:

- "Qualified requesters may obtain copies of this report from DDC."
- (2) "Foreign announcement and dissemination of this report by DDC is not authorized."
- (3) "U. S. Government agencies may obtain copies of this report directly from DDC. Other qualified DDC users shall request through
- (4) "U. S. military agencies may obtain copies of this report directly from DDC. Other qualified users shall request through
- (5) "All distribution of this report is controlled. Qualified DDC users shall request through

If the report has been furnished to the Office of Technical Services, Department of Commerce, for sale to the public, indicate this fact and enter the price, if known.

- 11. SUPPLEMENTARY NOTES: Use for additional explana-
- 12. .SPONSO: ING MILITARY ACTIVITY: Enter the name of the departmental project office or laboratory sponsoring (paying for) the research and development. Include address.
- 13. ABSTRACT: Enter an abstract giving a brief and fact al summary of the document indicative of the report, sen trough it may also appear elsewhere in the body of the technical report. If additional space is required, a continuation sheet shall be attached.

It is highly desirable that the abstract of classified reports be unclassified. Each paragraph of the abstract shall end with an indication of the military security classification of the information in the paragraph, represented as (TS). (S). (C), or (U).

There is no limitation on the length of the abstract. However, the suggested length is from 150 to 225 words.

14. KEY WORDS: Key words are technically meaningful terms or short phrases that characterize a report and may be used as index entries for cataloging the report. Key words must be selected so that no security classification is required. Identifiers, such as equipment model designation, trade name, military project code name, geographic locations may be used as key words but will be followed by an adjustion of technical context. The assignment of links were and weights is optional.